

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Heritage Environmental Venice Staging Area	Facility Location ID:	VenW01
Assessment Date :	8/13/2010	Incident Name :	BP Spill
Physical Location :	308 Halliburton Road		
City, State :	Venice, LA	County :	Plaquemines

ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
5. How many samples were collected?	1
Additional Comments : <p>A brief site walk was conducted identifying sampling locations (frac tank #265771). Heritage indicated that they have 3 frac tanks containing BP liquid wastes on site. Several other filled frac tanks are located on the site, but are not associated with BP. All frac tanks on site received water (as needed) as ballast prior to the evacuation ordered for 8/11/2010 ? 8/12/2010. All rollofs located on site are empty; all rollofs were loaded out for disposal prior to the evacuation ordered for 8/11/2010 ? 8/12/2010. Heritage personnel were actively reconstructing decon pads for processing boom, lining rolloff containers, and removing storm water from the secondary containments of the fract tanks. Personnel</p> <p>WASR collected one liquid waste sample (with field duplicate) from frac tank #265771. Split samples were provided to BP's environmental contractor.</p>	